


1A 1B 1C

**-ELS-LW1  
P-TRAP w/CLEANOUT**

**COMPLETE  
ASSEMBLY**



10A 10B 10C

**-ELS-OS-LW1  
P-TRAP w/CLEANOUT**

**COMPLETE  
ASSEMBLY**

**PARTS ARE SHIPPED  
LOOSE FOR FIELD ASSEMBLY.**

1A	4945-001-001	-ELS-LW1 1" WALL, WASTE CONN ASSY	10A	4940-001-001	-ELS-OS-LWS1 1" WALL, WASTE CONN ASSY
1B	4945-008-001	-ELS-LW1 8" WALL, WASTE CONN ASSY	10B	4940-008-001	-ELS-OS-LWS1 8" WALL WASTE CONN ASSY
1C	4945-013-001	-ELS-LW1 12" WALL, WASTE CONN ASSY	10C	4940-013-001	-ELS-OS-LWS1 12" WALL WASTE CONN ASSY
2	1803-041-000	1-1/4" DWV WROT COPPER ADAPTER	11	1803-051-000	1-1/2" DWV WROT COPPER ADAPTER
3A	2125-006-750	1-1/4" OD x 6-3/4" CU TUBE -1" WALL	12A	2126-006-750	1-1/2" OD x 6-3/4" CU TUBE -1" WALL
3B	2125-013-750	1-1/4" OD x 13-3/4" CU TUBE -8" WALL	12B	2126-013-750	1-1/2" OD x 13-3/4" CU TUBE -8" WALL
3C	2125-018-750	1-1/4" OD CU TUBE -12" WALL	12C	2126-018-750	1-1/2" OD x 18-3/4" CU TUBE -12" WALL
4	1740-041-000	1-1/4" 90° ELL WROT COPPER	13	1740-051-000	1-1/2" 90° ELL WROT COPPER
5	2125-003-625	1-1/4" OD x 3-5/8" COPPER TUBE	14	2126-003-625	1-1/2" x 3-5/8" COPPER TUBE
6	1851-041-000	1-1/4" SOLDER CAST BRASS DWV P-TRAP	15	1851-051-000	1-1/2" SOLDER CAST BRASS P-TRAP
7	2125-002-199	1-1/4" OD x 2" COPPER TUBE	16	2126-002-000	1-1/2" x 2" COPPER TUBE
8	1835-041-000	ASA CLEANOUT PLUG	17	1835-051-000	ASA CLEANOUT PLUG
9	1771-041-000	1-1/4" CAST BRONZE DWV TEE	18	1771-051-199	1-1/2" CAST BRONZE DWV TEE
ITEM	PART NUMBER	DESCRIPTION	ITEM	PART NUMBER	DESCRIPTION



**ACORN ENGINEERING COMPANY**  
P.O. BOX 3527 INDUSTRY, CA. 91744  
(626) 336-4561 FAX (626) 961-2200

**TITLE LAVY THRU-WALL EXTENSION, P-TRAP w/CLEANOUT 1-1/4" & 1-1/2" NPT**

MANUFACTURE DATE  
**APRIL 1972  
TO APRIL 30, 1998**

DATE ISSUED  
**09/01/89**  
DATE REVISED  
**07/18/01**

DRAWING NUMBER  
**9985-300-001**