



INSTALLATION INSTRUCTIONS:

A-ROUGH-IN FOR THE FOLLOWING:

- 1/2" NPT HOT AND COLD SUPPLIES (1) BY OTHERS.
- 1-1/2" OD WASTE OUTLET (2) BY OTHERS FOR GRID STRAINER & 1-1/4" OD TAILPIECE PROVIDED (3) BY OTHERS OR OPTIONAL -TPT TUBULAR P-TRAP
- ø3/8" MOUNTING POINTS (4) FOR UNDER COUNTER BRACKETS PROVIDED FOR WALL ANCHORS AND ANCHORING HARDWARE OTHERS (5).
- OPTIONAL -TE TRAP ENCLOSURE (6) MOUNTING HOLES (7) FOR WALL ANCHORS AND ANCHORING HARDWARE (5) BY OTHERS.

B-LAYOUT AND INSTALL WALL ANCHORS BY OTHERS AND ANCHORING S-CLIP PROVIDED AS INDICATED.

FOR -SO SENSOR OPERATION

SUPPLY 120VAC, 60Hz, 3AMP (MAX.) GFCI PROTECTED, ELECTRICAL RECEPTACLE (8).

C- POSITION FIXTURE INTO PLACE AND SECURE TO WALL USING WASHERS AND NUTS BY OTHERS. MAKE UP SUPPLY AND WASTE CONNECTIONS AS REQUIRED.

WARNING: SUPPLY LINES SHOULD BE FLUSHED OF ALL FOREIGN MATERIAL SUCH AS DOPE, CHIPS, SOLDER ETC. MAXIMUM RECOMMENDED OUTLET WATER TEMPERATURE IS 105° F.

NOTE:

TRANSFORMER(S) MUST BE WIRED TO A GFI PROTECTED CIRCUIT. FIXTURE MUST BE EARTH GROUNDED PER N.E.C. (NATIONAL ELECTRICAL CODE)

 WHITEHALL MANUFACTURING P.O. BOX 3527 Industry, CA 91744 15125 Proctor Ave Industry, CA 91746 (626) 968-6681 FAX (626) 855-4862	TITLE CORNER INFECTION PREVENTION SINK #4160	
	MANUFACTURE DATE SEPTEMBER 2016 TO PRESENT	DATE ISSUED 09/12/16